

Face ground
at 90°

Nick with corner
of grinding wheel.

Grind away less than half

$\frac{3}{4}$ "

etc - or

Shaft of dia you can
grab with your TS Chuck
Silver brazed to blank.
(Drill blind hole in slug
of $\frac{3}{4}$ material to allow
brazing of shaft.)

