






Set Mortising Gauge points to size of Chisel—hand or machine



Center pins on work as best as you can by eye.

© ERC-2007



Mark with the same setting from the opposite side.

You are left with two sets of lines as shown above. Centering the points in the center of these lines will leave you with a perfectly centered layout. Better than you are getting with fractions. Layout mortises and tenons then adjust tools to layout.