


As received from Sharpening shop



After careful sharpening with Makita 9820-2.
Light gap of 0.001 inch measured with feeler gauge.

