



Top of sill must locate $\frac{3}{4}$ " above finish floor

$\frac{3}{4}$ " finish floor

top of subfloor

Remove framing in this area

6.625 j 1.75 d qlon o sill



Acorn Woodworks, Inc.

320 Parkway Circle
 P.O. Box 468
 Westfield, Indiana 46074

www.acornwoodworks.com
 317-867-4377
 Fax 317-867-5369